




STS-106 (FD03)





STS-106 (FD03)





STS-106 (FD03)






FLT PLAN/106/FLIGHT

STS-106 (FD03)

T D R S E W	D O R B	MET Day 001	RRS I GGTS SSSS CTAA MLTT DMII	MS2 R. MASTRACCHIO	MS3 D. BURBANK	MS4 Y. MALENCHENKO	MS5 B. MORUKOV	MCC NOTES
				~	~	~	~	
~	~	20:00		<u>RNDZ PGSC RECONFIG</u> Configure PGSCs for Docked ops. L17 Check MCIU filter screen	<u>EVA 1 PRE-EVA TOOL CONFIG</u> (EVA, <u>TOOLS/TL</u>)	<u>EVA 1 PRE-EVA TOOL CONFIG</u> (EVA, <u>TOOLS/TL</u>)	<u>RNDZ PGSC RECONFIG</u> Configure PGSCs for Docked ops. SWAP DRILL BATTERIES	
4 3 0	~	21:00		<u>SAFER CHECKOUT</u> (EVA, <u>CHECKOUTS</u>)	<u>SAFER CHECKOUT</u> (EVA, <u>CHECKOUTS</u>)	<u>EVA 1 PRE-EVA TOOL CONFIG</u> (EVA, <u>TOOLS/TL</u>)	<u>SHUTTLE/ISS H2O CNTR FILL</u> (ORB OPS, <u>ECLS</u>) Init CWC fill #2.	
~	~	22:00		EXERCISE	<u>MASK PREBREATHE TERMINATE</u> (EVA, <u>10.2 PSI CABIN</u>)	<u>MASK PREBREATHE TERMINATE</u> (EVA, <u>10.2 PSI CABIN</u>)	<u>SHUTTLE/ISS H2O CNTR FILL</u> (ORB OPS, <u>ECLS</u>) Terminate CWC fill #2.	
5 3 1	~	23:00		<u>EVA 1 BRIEFING CARD</u> (EVA, <u>TOOLS/TL</u>)	<u>EVA 1 BRIEFING CARD</u> (EVA, <u>TOOLS/TL</u>)	<u>EVA 1 BRIEFING CARD</u> (EVA, <u>TOOLS/TL</u>)	<u>EVA 1 BRIEFING CARD</u> (EVA, <u>TOOLS/TL</u>)	
~	~	00:00		<u>EPCS DEACT</u> (ISS OPS, <u>JOINT</u>)	OFF DUTY	OFF DUTY	OFF DUTY	
				OFF DUTY				

STS-106 (FD03)



STS-106 (FD03)

